


# WIRING DIAGRAM FOR ANALOG HOUR METER

**331-511**



PART NO. 331-511B